

DB 1240


DATE - 16/09/2025

CERTIFICATE OF STABILITY

1. Name of Building : Queen's School Building
2. Name of applicant : Principal Queen's School Building
3. Address : S.NO. 88 P, Nandkheda Road Parbhani
4. Year of Construction : 2008
5. Date of Inspection : 09/09/2025

This is to certify that I have inspected the premises and examined the various parts of structure i.e beam, columns and its junction and all functional elements of the structure.

I am of the opinion that all the works of engineering and construction in premises are structurally sound and its stability will not be endangered if used further. The structure is in excellent condition and can be used further to fulfill functional requirements.


Sub-Divisional Engineer
PW Sub-Division (H.Q.)
PARBHANI

Copy, Principal Queen's School Parbhani Nandkheda Road Parbhani Information